

## Software History

### Industrial Ethernet Tx

Version	Date	History
5.12	21.12.23	- Fixed a bug where Ethernet/IP stack lost its IP-Address during Firmware update.
5.10	22.09.23	- Profinet Telegram 9 data consistency for drive start command and drive parameter like position and speed improved. - Removed space at the end of pdo names in eds
5.08	12.06.23	- Ethernet/IP profile position mode support
5.06	31.03.23	- EoE support - Ethernet speed improvements
5.04	24.11.22	- Profinet support - New SDO Objects corresponding to ASCII-Commands <ul style="list-style-type: none"><li>○ 0x6068</li><li>○ 0x5001:42</li></ul>
5.02	17.08.22	- Renamed servo controller from Tx to Tvi. Note that an interim SW version is required to update from 5.00 to 5.02.
5.00	07.07.22	- Initial version with EtherCAT and TCP/IP support.